


P 06 045 SUPERSEDED BY P 06 081

P 06 045 (WVA 23347) → P 06 081 (WVA 23313)

Following the replacement that have occurred in the OES at BMW, Brembo P 06 045 will be replaced by P 06 081. All vehicles previously fitted with P 06 045 will now be covered by P 06 081.

P 06 081 is thus retroactively applicable for all linked vehicles.



The difference is the lack of the piston clip on the pad with WVA 23313 vs 23347