


# P 23 086 SUPERSEDED BY P 23 145


## P 23 086 WVA (23711-23712) → P 23 145 (WVA 23711-23713)

For the reference P 23 086, Fiat changed the corresponding OES reference from one wear indicator to two wear indicators per set. Wear indicators that are not used have to be simply cut off during assembly. Brembo will perform the same change, according to the OES programme. P 23 086 will be replaced by P 23 145

### P 23 086



### P 23 145



Existing stock of P 23 086 can be sold out. Please consider that P 23 086 can be used only for vehicles equipped with one wear indicator.