



P 61 090 SUPERSEDED BY P 23 143

For the reference P 61 090, Fiat changed the corresponding OES references from one wear indicator to two wear indicators per set. Wear indicators not used have to be simply cut off during assembly. Brembo will perform the same change, according to the OES programme. P 61 090 will be replaced by P 23 143.

P 61 090



P 23 143



Existing stock of P 61 090 can be sold out. Please used only on vehicles equipped with one wear indicator.