



P 61 093 SUPERSEDED BY P 23 136

For the references P 61 093, Fiat changed the corresponding OES references from one wear indicator to two wear indicators per set. Wear indicators that are not used have to be simply cut off during assembly. Brembo will perform the same change, according to the OES programme. P 61 093 will be replaced by P 23 136.



Existing stock of P 61 093 can be sold out. Please consider that P 61 093 can be used only on vehicles equipped with one wear indicator.