


# P 06 031 SUPERSEDED BY P 06 054

**P 06 031 (WVA 23347) → P 06 054 (WVA 23313)**

Due to changes, which have been made on OES side of BMW, the following replacement will be done:



P 06 054 is applicable retroactively for all vehicles. The only difference between both parts is the finger side clips, which are removed now with P 06 054 for all vehicles.