

Datos técnicos de la pinza

| | |
|-----------------------------|------------------------------------|
| Eje Trasero | Diámetro pistones 38 mm |
| Número pistones 1 | Sistema de frenos LUCAS |
| Posición Left | Código EAN 8020584504291 |



Vehículos compatibles

| LANCIA | | | | |
|--------------------|--|-----|-------------|--|
| Modelo | Tipo | Kw | Año | |
| KAPPA (838_) | 2.0 16V Turbo (838AB1AA) | 151 | 02/95 10/01 | |
| KAPPA (838_) | 2.0 20V (838AA1AA) | 107 | 10/94 10/01 | |
| KAPPA (838_) | 2.0 20V (838AG1AA, 838AG11A) | 114 | 07/96 10/01 | |
| KAPPA (838_) | 2.0 20V Turbo (838AM1AA) | 162 | 06/98 10/01 | |
| KAPPA (838_) | 2.4 20V (838AC1AA, 838AC11A) | 129 | 08/94 10/01 | |
| KAPPA (838_) | 2.4 JTD (838AL1AA) | 100 | 06/98 10/01 | |
| KAPPA (838_) | 2.4 T.DS (838AE1AA, 838AH1AA) | 91 | 08/94 10/01 | |
| KAPPA (838_) | 3.0 24V (838AD1AA, 838AD11A, 838XD1AA, 838ZD1AA) | 150 | 08/94 10/01 | |
| KAPPA Coupe (838_) | 2.0 16V Turbo (838CB) | 151 | 11/96 03/01 | |
| KAPPA Coupe (838_) | 2.0 20V Turbo (838CM) | 162 | 06/98 03/01 | |
| KAPPA Coupe (838_) | 2.4 20V (838CC) | 129 | 11/96 03/01 | |
| KAPPA Coupe (838_) | 3.0 24V (838CD, 838CD11A) | 150 | 11/96 03/01 | |
| KAPPA SW (838_) | 2.0 16V Turbo (838BB1AA) | 151 | 07/96 10/01 | |
| KAPPA SW (838_) | 2.0 20V (838BG1AA) | 114 | 07/96 10/01 | |
| KAPPA SW (838_) | 2.0 20V Turbo (838BM1AA) | 162 | 06/98 10/01 | |
| KAPPA SW (838_) | 2.4 20V (838BC1AA, 838BC11A) | 129 | 07/96 10/01 | |
| KAPPA SW (838_) | 2.4 JTD (838BL1AA) | 100 | 06/98 10/01 | |
| KAPPA SW (838_) | 2.4 T.DS (838BH1AA) | 91 | 07/96 10/01 | |

Códigos OE

Códigos OE compatibles

| | |
|--------|---------|
| LANCIA | 9946571 |
|--------|---------|

| | |
|--------|---------|
| LANCIA | 9947542 |
|--------|---------|
