

Étrier de frein rénové F 49 001



Caractéristiques techniques de l'étrier de frein rénové

Essieu Avant

Diamètre des pistons
54 mm

Nombre de pistons
1

Système de freinage
SUMITOMO

Position
Right

Code EAN
8020584511923



Véhicules couverts

MAZDA

Modèle	Type	kW	Année
323 C IV (BG)	1.3	49	09/89 07/94
323 C IV (BG)	1.3 16V	54	09/89 07/94
323 C IV (BG)	1.6	62	09/89 06/91
323 C IV (BG)	1.6 16V	65	03/91 10/94
323 C IV (BG)	1.7 D	41	08/89 07/94
323 C V (BA)	1.3 16V	54	08/94 09/98
323 F IV (BG)	1.6	66	04/91 04/94
323 F IV (BG)	1.6	62	09/89 06/91
323 F IV (BG)	1.6 16V	65	03/91 10/94
323 F IV (BG)	1.8 16V	76	08/89 07/94
323 F IV (BG)	1.8 4WD	76	01/91 04/94
323 P V (BA)	1.3 16V	54	10/96 09/98
323 S IV (BG)	1.3	49	09/89 06/91
323 S IV (BG)	1.3 16V	54	04/91 07/94
323 S IV (BG)	1.6	64	06/89 03/91
323 S IV (BG)	1.6	62	09/89 06/91
323 S IV (BG)	1.6 16V	65	08/89 10/96
323 S IV (BG)	1.7 D	41	08/89 07/94
323 S V (BA)	1.3 16V	54	08/94 09/98

Refs constructeur

Références constructeurs compatibles

MAZDA	B10733610
MAZDA	B107-33-610
MAZDA	B10733610A
MAZDA	B107-33-610A
MAZDA	B10733980
MAZDA	B107-33-980
MAZDA	B4603361X
MAZDA	B460-33-61X
MAZDA	B46033980B
MAZDA	B460-33-980B
MAZDA	BC8W3361
MAZDA	BC8W-33-61
MAZDA	BC8W3361X
MAZDA	BC8W-33-61X
MAZDA	BCZW3398Z
MAZDA	BCZW-33-98Z
MAZDA	BCZW3398ZA
MAZDA	BCZW-33-98ZA