

Étrier de frein rénové F 49 010



Caractéristiques techniques de l'étrier de frein rénové

Essieu Avant

Diamètre des pistons
54 mm

Nombre de pistons
1

Système de freinage
SUMITOMO

Position
Left

Code EAN
8020584512012



Véhicules couverts

MAZDA			
Modèle	Type	kW	Année
323 C IV (BG)	1.3 16V	54	09/89 07/94
323 C IV (BG)	1.6	62	09/89 06/91
323 C V (BA)	1.5 16V	65	08/94 09/98
323 C V (BA)	1.8 16V	84	08/94 09/98
323 F IV (BG)	1.6	62	09/89 06/91
323 F IV (BG)	1.8 4WD	76	01/91 04/94
323 F V (BA)	1.5 16V	65	07/94 09/98
323 P V (BA)	1.5 16V	65	10/96 09/98
323 S IV (BG)	1.3 16V	54	04/91 07/94
323 S IV (BG)	1.6	64	06/89 03/91
323 S IV (BG)	1.6	62	09/89 06/91
323 S V (BA)	1.5 16V	65	08/94 09/98

Refs constructeur

Références constructeurs compatibles

MAZDA	B4623371X
MAZDA	B462-33-71X
MAZDA	B46233990B
MAZDA	B462-33-990B
MAZDA	B4623399Z
MAZDA	B462-33-99Z

MAZDA	B4623399ZB
MAZDA	B462-33-99ZB
MAZDA	BR703371X
MAZDA	BR70-33-71X
MAZDA	G11333990
MAZDA	G113-33-990
MAZDA	G11333990A
MAZDA	G113-33-990A