

Étrier de frein rénové F 61 076



Caractéristiques techniques de l'étrier de frein rénové

Essieu Avant

Diamètre des pistons
48 mm

Nombre de pistons
1

Système de freinage
BENDIX

Position
Left

Code EAN
8020584523070



Véhicules couverts

PEUGEOT

| Modèle | Type | kW | Année |
|---------------------|---------|----|-------------|
| 305 II (581M) | 1.6 | 69 | 10/82 06/88 |
| 305 II (581M) | 1.6 | 54 | 11/86 12/88 |
| 305 II (581M) | 1.9 | 72 | 11/86 12/88 |
| 305 II Break (581E) | 1.6 | 71 | 09/83 06/84 |
| 309 I (10C, 10A) | 1.1 | 40 | 10/85 07/89 |
| 309 I (10C, 10A) | 1.3 | 47 | 10/85 07/89 |
| 309 I (10C, 10A) | 1.3 XL | 52 | 09/86 08/89 |
| 309 I (10C, 10A) | 1.4 | 49 | 03/89 07/89 |
| 309 I (10C, 10A) | 1.4 | 55 | 03/89 07/89 |
| 309 I (10C, 10A) | 1.4 | 48 | 10/85 08/88 |
| 309 I (10C, 10A) | 1.5 | 63 | 06/87 12/89 |
| 309 I (10C, 10A) | 1.6 | 69 | 01/86 07/89 |
| 309 I (10C, 10A) | 1.6 | 83 | 07/86 06/89 |
| 309 I (10C, 10A) | 1.6 | 59 | 10/85 07/89 |
| 309 I (10C, 10A) | 1.6 Cat | 55 | 09/86 12/89 |
| 309 I (10C, 10A) | 1.9 D | 47 | 06/86 07/89 |
| 309 I (10C, 10A) | 1.9 GTI | 88 | 07/88 07/89 |
| 309 I (10C, 10A) | 1.9 GTI | 94 | 10/86 07/89 |
| 309 II (3C, 3A) | 1.1 | 40 | 09/89 10/93 |
| 309 II (3C, 3A) | 1.6 | 68 | 07/89 12/93 |
| 309 II (3C, 3A) | 1.6 | 69 | 07/89 12/93 |

| | | | |
|-----------------|-------------|-----|-------------|
| 309 II (3C, 3A) | 1.6 GTi | 85 | 09/89 10/93 |
| 309 II (3C, 3A) | 1.8 D | 43 | 10/91 10/93 |
| 309 II (3C, 3A) | 1.8 Diesel | 44 | 07/89 12/93 |
| 309 II (3C, 3A) | 1.8 TD | 57 | 08/89 12/93 |
| 309 II (3C, 3A) | 1.9 D | 50 | 09/89 10/93 |
| 309 II (3C, 3A) | 1.9 GTI 16V | 116 | 08/89 07/90 |

Refs constructeur

Références constructeurs compatibles

PEUGEOT 440068