

# Renoverat bromsok F 83 073



## Tekniska data för det renoverade bromsoken

**Axel** Fram


**Kolv diameter**  
57 mm

**Antal kolvar**  
1

**Bromssystem**  
HOSEI

**Position**  
Right

**EAN-kod**  
8020584528723



## Kompatibla fordon

### TOYOTA

Modell	Typ	kW	År
CALDINA Estate (_T19_)	2.0 TD (CT190G)	54	06/94 09/97
CARINA E (_T19_)	1.6 (AT190)	73	12/93 09/97
CARINA E (_T19_)	1.6 (AT190)	85	12/93 09/97
CARINA E (_T19_)	1.6 16V (AT190_)	78	10/95 09/97
CARINA E (_T19_)	1.6 GLI (AT190)	79	04/92 09/97
CARINA E (_T19_)	1.8 (AT191)	79	01/95 09/97
CARINA E (_T19_)	2.0 D (CT190)	54	04/92 01/96
CARINA E (_T19_)	2.0 TD (CT190)	61	01/96 09/97
CARINA E Saloon (_T19_)	1.6 (AT190)	79	01/93 09/97
CARINA E Saloon (_T19_)	1.6 (AT190)	73	01/95 09/97
CARINA E Saloon (_T19_)	1.6 (AT190)	78	10/95 09/97
CARINA E Saloon (_T19_)	1.6 16V (AT190_)	85	12/94 09/97
CARINA E Saloon (_T19_)	1.8 i 16V (AT191)	79	01/95 09/97
CARINA E Saloon (_T19_)	2.0 D (CT190)	54	08/92 01/96
CARINA E Saloon (_T19_)	2.0 TD (CT190_)	61	01/96 09/97
CARINA E Sportswagon (_T19_)	1.6	85	04/92 09/97
CARINA E Sportswagon (_T19_)	1.6 GLI (AT190_)	79	01/93 09/97
CARINA E Sportswagon (_T19_)	1.6 i (AT190_)	73	02/95 09/97
CARINA E Sportswagon (_T19_)	1.8 i (AT191_)	79	02/95 09/97
CARINA E Sportswagon (_T19_)	2.0 D (CT190_)	54	01/93 01/96

CARINA E Sportswagon (_T19_)	2.0 TD (CT190_)	61	01/96 09/97
CELICA Coupe (_T20_)	1.8 i 16V (AT200/ST)	85	11/93 11/99
CORONA Hatchback	1.8	92	02/92 01/96
CORONA Saloon (_T19_)	1.8 (ST190_)	92	10/91 01/96

## OE-nummer

### Kompatibla OE-nummer

TOYOTA	4773020480
TOYOTA	47730-20480