
P83 081 SUPERSEDED BY **P83 109**

P 83 081 (WVA 24204) -> P 83 109 (WVA 24668)


Toyota just decided to replace their version of P 83 081 into P 83 109. We will follow the same route and make the same supersession. Therefore P 83 109 will cover all applications of P 83 081 in the future and can be fitted retrospectively.

As you can see in the picture below P 83 109 comes with a smaller friction shape as P 83 081.





P83109



Existing stock of P 83 081 can be sold out.

