

Dane techniczne zacisku regenerowanego

Oś Przód	Średnica tłoka 60 mm
Liczba tłoków 1	Układ hamulcowy ASCO
Pozycja Left	Referencja EAN 8020584528051



Pasujące pojazdy

TOYOTA

Model	Typ	kW	Rok
HIACE II Box (LH5_, YH7_, LH7_, LH6_, YH6_, YH5_)	1.8 (YN5_, YH50_, YH60_)	58	12/82 07/89
HIACE II Box (LH5_, YH7_, LH7_, LH6_, YH6_, YH5_)	2.0 (YH6_, YN5)	65	12/82 07/89
HIACE II Box (LH5_, YH7_, LH7_, LH6_, YH6_, YH5_)	2.2 D (LH7_, LH5_, LH3_, LH50_, LH60_)	49	12/82 11/89
HIACE II Box (LH5_, YH7_, LH7_, LH6_, YH6_, YH5_)	2.4 D (LH7_, LH6_, LH5_)	55	05/84 11/89
HIACE II Wagon (LH7_, LH5_, LH6_, YH7_, YH6_, YH5_)	1.8 (H5G)	58	03/83 11/89
HIACE II Wagon (LH7_, LH5_, LH6_, YH7_, YH6_, YH5_)	2.0 (YH51_, YH61_)	65	01/85 08/89
HIACE II Wagon (LH7_, LH5_, LH6_, YH7_, YH6_, YH5_)	2.2 D (H5G)	49	03/83 11/89
HIACE II Wagon (LH7_, LH5_, LH6_, YH7_, YH6_, YH5_)	2.4 D (H5G)	55	08/84 08/89
HILUX V Pickup (_N_, KZN1_, VZN1_)	1.8 (YN5_, YN8_, YN85)	61	09/88 06/98
HILUX V Pickup (_N_, KZN1_, VZN1_)	2.4 D (LN90_)	58	03/95 08/97
HILUX VI Pickup (_N1_)	2.4 D (LN150, LN145)	55	08/97 04/05
HILUX VI Pickup (_N1_)	2.5 D-4D (KDN14_, KDN15_, KDN16_, KDN19_)	65	11/01 07/05

VW

Model	Typ	kW	Rok
TARO	2.4 D	61	06/89 03/97
TARO	2.4 D	58	07/94 03/97

Numery OE

Pasujące kody OE

TOYOTA	4775026040
--------	------------

TOYOTA	4775026080
--------	------------

TOYOTA	4775035130
--------	------------

VW	J4775026080
----	-------------
