

Tekniska data för det renoverade bromsoken

Axel Fram

Kolv diameter
54 mm

Antal kolvar
1

Bromssystem
SUMITOMO

Position
Left

EAN-kod
8020584536797



Kompatibla fordon

MAZDA

| Modell | Typ | kW | År |
|---------------|---------|----|-------------|
| 323 C IV (BG) | 1.3 | 49 | 09/89 07/94 |
| 323 C IV (BG) | 1.3 16V | 54 | 09/89 07/94 |
| 323 C IV (BG) | 1.6 | 62 | 09/89 06/91 |
| 323 C IV (BG) | 1.6 16V | 65 | 03/91 10/94 |
| 323 C IV (BG) | 1.7 D | 41 | 08/89 07/94 |
| 323 C V (BA) | 1.3 16V | 54 | 08/94 09/98 |
| 323 F IV (BG) | 1.6 | 66 | 04/91 04/94 |
| 323 F IV (BG) | 1.6 | 62 | 09/89 06/91 |
| 323 F IV (BG) | 1.6 16V | 65 | 03/91 10/94 |
| 323 F IV (BG) | 1.8 16V | 76 | 08/89 07/94 |
| 323 F IV (BG) | 1.8 4WD | 76 | 01/91 04/94 |
| 323 P V (BA) | 1.3 16V | 54 | 10/96 09/98 |
| 323 S IV (BG) | 1.3 | 49 | 09/89 06/91 |
| 323 S IV (BG) | 1.3 16V | 54 | 04/91 07/94 |
| 323 S IV (BG) | 1.6 | 64 | 06/89 03/91 |
| 323 S IV (BG) | 1.6 | 62 | 09/89 06/91 |
| 323 S IV (BG) | 1.6 16V | 65 | 08/89 10/96 |
| 323 S IV (BG) | 1.7 D | 41 | 08/89 07/94 |
| 323 S V (BA) | 1.3 16V | 54 | 08/94 09/98 |

OE-nummer

Kompatibla OE-nummer

| | |
|-------|--------------|
| MAZDA | B10733710 |
| MAZDA | B107-33-710 |
| MAZDA | B10733710A |
| MAZDA | B107-33-710A |
| MAZDA | B10733990 |
| MAZDA | B107-33-990 |
| MAZDA | B4603371X |
| MAZDA | B460-33-71X |
| MAZDA | B46033990B |
| MAZDA | B460-33-990B |
| MAZDA | BC8W3371 |
| MAZDA | BC8W-33-71 |
| MAZDA | BC8W3371X |
| MAZDA | BC8W-33-71X |
| MAZDA | BCZW3399Z |
| MAZDA | BCZW-33-99Z |
| MAZDA | BCZW3399ZA |
| MAZDA | BCZW-33-99ZA |