

Tekniska data för det renoverade bromsoken

Axel Fram

Kolvdiometer
43 mm

Antal kolvar
4

Bromssystem
SUMITOMO

Position
Left

EAN-kod
8020584528679



Kompatibla fordon

TOYOTA

Modell	Typ	kW	År
4 RUNNER (_N1_)	3.0 (VZN130_)	105	01/90 10/95
HILUX Closed Off-Road Vehicle (LN_, KZN1_, VZN1_)	2.4 TD 4WD (LN130_)	92	08/88 08/97
HILUX V Pickup (_N_, KZN1_, VZN1_)	2.2 (YN106_, YN110_)	69	03/89 07/94
HILUX V Pickup (_N_, KZN1_, VZN1_)	2.4 D (LN5_, LN85, LN90)	55	10/88 07/97
HILUX V Pickup (_N_, KZN1_, VZN1_)	2.4 D (LN5_, LN85_, LN90_, LN14_, LN15_)	59	10/91 07/97
HILUX V Pickup (_N_, KZN1_, VZN1_)	2.4 D (LN85_, LN110, Ln90)	61	09/88 08/97
HILUX V Pickup (_N_, KZN1_, VZN1_)	2.4 D 4WD (LN1_)	61	09/88 08/97
HILUX V Pickup (_N_, KZN1_, VZN1_)	2.4 D 4WD (LN105_, LN108_, LN110_)	55	09/94 07/97
HILUX V Pickup (_N_, KZN1_, VZN1_)	2.4 D 4WD (LN110_)	58	01/94 12/97
HILUX V Pickup (_N_, KZN1_, VZN1_)	2.4 i 4WD (RN106_, RN110_)	84	01/89 07/97
HILUX VI Pickup (_N1_)	2.4 i 4WD (RZN14_, RZN16_, RZN19_)	103	08/97 10/05
HILUX VI Pickup (_N1_)	2.4 TD 4WD (LN165_, LN170_, LN190_)	66	08/98 01/02
HILUX VI Pickup (_N1_)	2.5 D-4D 4WD (KDN165_, KDN170_, KDN190_)	75	11/01 07/05
LAND CRUISER (_J7_)	3.0 TD (KZJ70_, KZJ73_, KZJ77_)	92	05/93 05/96
LAND CRUISER (_J7_)	4.2 D (HZJ76, HZJ78, HZJ70, HZJ73, HZJ75, HZJ79, HZJ77)	96	01/90 -
LAND CRUISER (_J7_)	4.2 D 4x4 (HZJ74, HZJ78, HZJ75)	123	08/90 08/01
LAND CRUISER 80 (_J8_)	3.5 D	85	01/90 08/92
LAND CRUISER Pickup (_J7_)	4.2 D 4x4 (HZJ7__V)	96	01/90 02/07

OE-nummer

Kompatibla OE-nummer

TOYOTA	4775035080
--------	------------

TOYOTA	47750-35080
--------	-------------

TOYOTA	4775035140
--------	------------

TOYOTA	47750-35140
--------	-------------